



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 20, 2013

Reviewed: 

Mine Name: Bright 1 & 2	Permit Number: M/021/0030
Operator Name: Neil Bradshaw	Inspection Date: May 7, 2013
Inspector(s): Lynn Kunzler	Time: 11:00 am
Other Participants:	Mine Status: active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine inspection.

Inspection Summary:


The annual permit fee has not been paid this year. The reclamation surety is due for escalation in December of this year. There has been recent activity at this site. Mr. Bradshaw's son in law showed up as I was leaving. I explained why I was there and asked him to pass on to Mr. Bradshaw that he needed to remit the annual permit fee ASAP.

The area was free of debris. Sediment control was working (raining during this inspection, and no runoff was occurring).

Photos were taken to document site conditions

Conclusions and Recommendations:

If permit fees are not received soon, then enforcement action should be considered. The Division needs to escalate the reclamation surety for this site and inform the operator of the amount now needed to be posted by December.

Inspector's Signature 

cc: Neil Bradshaw, Operator

Ed Ginouves, BLM (Eginouves@blm.gov)

O:\M021-Iron\M0210030-Bright 1&2\Inspections\Insp-05072013.doc